

# AJA Ki Pro Ultra Plus Release Notes – V5

## Release Notes v5.0

### Introduction

---

This firmware update is a major new feature release for Ki Pro Ultra Plus.

Be sure to consult the Installation and Operation Guide (user manual) for detailed information about features and configuration guidelines. The most current documentation can always be found in the Support section of [www.aja.com](http://www.aja.com).

### New Feature in v5.0

---

- Infinite Recording feature

### Fixes, Changes and Improvements in v5.0

---

- Enhanced RS-422 timecode operation
- Improved seams between segments
- Fixed issue with NDF timecode on DNxHD files
- Improved gang compatibility
- Fixed several issues around 2SI inputs and outputs

### Firmware Update Consideration

---

- AJA recommends a Factory Reset under the CONFIG menu prior to updating firmware.

- After a firmware update, the web browser (Safari, Firefox, etc.) may lose its connection. A refresh of the web browser will reconnect the web UI.
- Do not attempt firmware updates while recording is in progress. Be sure the device is in the stopped state before performing a firmware update.

## Technical Support

---

AJA Technical Support is free and available to help you answer questions or resolve issues with any of your AJA products.

### **To contact AJA Technical Support:**

Email: [support@aja.com](mailto:support@aja.com)

Phone: +1-530-271-3190

Fax: +1-530-274-9442

Web: <https://www.aja.com/support/contact>

Shipping: 180 Litton Dr. Grass Valley, CA 95945 USA