

AJA Ki Pro Ultra Plus Release Notes – V4.1

Release Notes – v4.1

Introduction

This firmware update is a major new feature release for Ki Pro Ultra Plus.

Be sure to consult the Installation and Operation Guide (user manual) for detailed information about features and configuration guidelines. The most current documentation can always be found in the Support section of www.aja.com.

Enhancements

Minor bug fixes and various improvements have been made, including:

- Resolved an issue in multi-channel ProRes 444 recording at 720p resolutions
- Resolved an issue for ProRes 444 playout via 2SI which was not working as expected
- Resolved an issue that caused some systems to lockup between playback and E-to-E
- Resolved an issue for gang recording where systems on the same network were not being identified
- ProRes playout AV sync has been improved
- Apple ProRes quad link skew improved to match SMPTE specification of 400ns*
- HDMI HFR support has been improved

*Apple ProRes only, AVID DNx supports the previous SMPTE specification of 40ns

Firmware Update Consideration

- AJA recommends a Factory Reset under the CONFIG menu prior to updating firmware.
- After a firmware update, the web browser (Safari, Firefox, etc.) may lose its connection. A refresh of the web browser will reconnect the web UI.
- Do not attempt firmware updates while recording is in progress. Be sure the device is in the stopped state before performing a firmware update.

Technical Support

AJA Technical Support is free and available to help you answer questions or resolve issues with any of your AJA products.

To contact AJA Technical Support:

Email: support@aja.com

Phone: +1-530-271-3190

Fax: +1-530-274-9442

Web: www.aja.com/support

Shipping: 180 Litton Dr. Grass Valley, CA 95945 USA