

AJA Ki Pro GO – Release Notes v3.2

Release firmware v3.2 for Ki Pro GO

Introduction

This firmware update is a maintenance release for the Ki Pro GO.

Be sure to consult the Installation and Operation Guide (user manual) for detailed information about features and configuration guidelines. The most current documentation can always be found in the Support section of www.aja.com.

Features, Updates and Improvements in v3.2

- Clips recorded at 25Hz, 24Hz or 23.98 Hz, while they would play back correctly on the Ki Pro GO, could experience performance issues while being scrubbed in external media players. This issue has been corrected.

Firmware Installation Considerations

- AJA recommends a Factory Reset under the CONFIG menu prior to updating firmware.
- After a firmware update, the web browser (Safari, Firefox, etc.) may lose its connection. A refresh of the web browser will reconnect the web UI
- Do not attempt firmware updates while recording is in progress. Be sure the device is in the stopped state before performing a firmware update.

Technical Support

AJA Technical Support is free and available to help you answer questions or resolve issues with any of your AJA products.

To contact AJA Technical Support:

Email: support@aja.com

Phone: +1-530-271-3190

Fax: +1-530-274-9442

Web: www.aja.com/support/contact

Shipping: 180 Litton Dr. Grass Valley, CA 95945 USA