

AJA Ki Pro GO Release Notes - v4.0.4

Firmware for Ki Pro GO

Introduction

Ki Pro GO v4.0.4 firmware is a maintenance release. It is highly recommended that you update firmware to avoid any potential issues.

Be sure to consult the Installation and Operation Guide (user manual) for detailed information about features and configuration guidelines. The most current documentation can always be found on the [Ki Pro GO Support page](#).

Features, Updates and Improvements in v4.0.4

- This maintenance release updates the Ethernet driver used in Ki Pro GO systems in the field with serial number 4KG002369 and up.

Firmware Installation Considerations

- AJA recommends performing a Factory Reset under the CONFIG menu prior to a firmware update.
- After a firmware update, the web browser (Safari, Firefox, etc.) may lose its connection to the Ki Pro GO. A refresh of the web browser will reconnect the web UI.
- Do not attempt firmware updates while recording is in progress. Be sure the device is in the stopped state before performing a firmware update.

Technical Support

AJA Technical Support is free and available to help you answer questions or resolve issues with any of your AJA products.

To contact AJA Technical Support:

Email: support@aja.com

Phone: +1-530-271-3190

Fax: +1-530-274-9442

Web: www.aja.com/support/contact

Shipping: 180 Litton Dr. Grass Valley, CA 95945 USA